

MONUMENT RECORD

CORNER I.D.

M - 21


STATE OF INDIANA - COUNTY OF MONROE

SECTION 26 27, TOWNSHIP 8 NORTH, RANGE 2 WEST

MONUMENT DESCRIPTION & REMARKS

PIPE PLACED FLUSH IN ROAD. IT WAS NOT CHECKED TO NORTH OR
SOUTH, BUT WAS CHECK-CHAINED TO EAST AND WEST 2642.64'
TO SE CORNER OF SW $\frac{1}{4}$.

RECOVERY TIE DRAWING



(●) AT CORNER

N

NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, _____ HEREBY CERTIFY THAT THIS
 DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE
 WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF
 THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND
 THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL
 THIS _____ DAY OF _____, 19 _____ A.D.

SPACE
 RESERVED
 FOR
 RECORDING
 OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:
VAN BUREN

CORNER I.D.

M - 21

28# 26# 34

NW, NW

NE, NW

NW, NE

NE, NE

SW, NW

SE, NW

SW, NE

SE, NE

NW, SW

NE, SW

NW, SE

NE, SE

SW, SW

SE, SW

SW, SE

SE, SE

2642.64

Van Bu-m21

AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74 SURVEY PARTY T. Daugherty - H. SUDBURY

COMMENTS Pipe placed flush in Road \perp - it was not checked to North or South, but was check-chained to East & West 2642.64 feet to SE corner of SW $\frac{1}{4}$

REFERENCE SKETCH (use back if ness.)

